

KEY 🗸 OK	× Requires Attention		ØN/A		
211D37052 BMW 840 G16 I M SPORT GRAN COUPE A 2998					
4 Doors	Saloon	Auto	Petrol	Previous Owners: 1	
Odometer Tax Expiry Chassis Number	131,761 km 31/07/2024 WBAGV22020CF465	47	Colour NCT Expiry Inspected	Black 27/01/2025 09/07/2024	
UNDER THE Coolant Level Brake Fluid Level Engine Oil Level Oil/Coolant Conta	1 1 1	<b>ENGINE RUN</b> Starts Engine Running Engine Smoking Aux Belt/Pulley No Exhaust Condition	1 1 1	INTERIOR A/C Receives Power Sat Nav Receives Power Radio Receives Power Power Windows Central Locking (excl key) Sunroof Electrics Spare Wheel	0044404
GENERAL OPERATION		TYRES		WARNING LIGHTS	
Brake Test Handbrake Efficier Steering Noise Static Gear Selectio Battery Health Suspension Ride Ho Drive Test	on J	OUTER N/S/F 4mm N/S/R 4mm O/S/F 4mm O/S/R 4mm Spare mm	MIDDLE INNER 4mm 4mm 4mm 4mm 4mm 4mm 4mm 4mm mm mm	Check Engine Light Oil Warning Light ABS Warning Light Brake Wear Indicator Airbag Warning Light	1 1 1 1
Clutch Slipping (Static)		BODY & INTERIOR CONDITI		<b>ON</b> Bodywork Grade	<u> </u>
NOTES					

Independent Vehicle Inspections carried out by



This report is subject to and in accordance with Autoguru Ireland Terms of Service which are available at www.autoguru.ie or by contacting us at info@autoguru.ie This report is generated based on the opinion of a qualified certified assessor and is to be used as advice only when considering the purchase of a vehicle. This report does not constitute a warranty or guarantee of any nature. Only areas of the vehicle that are accessible on the day of inspection can be checked. The certified assessor has been instructed to carry out a visual inspection and not to drive the vehicle on any public highway. Test drives are completed over 30 meters in 1st, 2nd gear and reverse only.

## **VEHICLE PHOTOGRAPHS**


















**VEHICLE SPLAT** 



Splat Key	
S2	Scratched
C	Stone Chips
P1	Panel Painted
TS	Tyre Sidewall Damaged

Independent Vehicle Inspections carried out by



This report is subject to and in accordance with Autoguru Ireland Terms of Service which are available at www.autoguru.ie or by contacting us at info@autoguru.ie This report is generated based on the opinion of a qualified certified assessor and is to be used as advice only when considering the purchase of a vehicle. This report does not constitute a warranty or guarantee of any nature. Only areas of the vehicle that are accessible on the day of inspection can be checked. The certified assessor has been instructed to carry out a visual inspection and not to drive the vehicle on any public highway. Test drives are completed over 30 meters in 1st, 2nd gear and reverse only.

Independent Vehicle Inspections carried out by



This report is subject to and in accordance with Autoguru Ireland Terms of Service which are available at www.autoguru.ie or by contacting us at info@autoguru.ie This report is generated based on the opinion of a qualified certified assessor and is to be used as advice only when considering the purchase of a vehicle. This report does not constitute a warranty or guarantee of any nature. Only areas of the vehicle that are accessible on the day of inspection can be checked. The certified assessor has been instructed to carry out a visual inspection and not to drive the vehicle on any public highway. Test drives are completed over 30 meters in 1st, 2nd gear and reverse only.